

From: [Jay Rao](#)
To: [WEISS, MICHAEL](#)
Subject: RE: Platform Henry Inspection Report
Date: Friday, December 13, 2019 9:14:51 AM

Hi Michael,
Good Morning. With regard to the area of concern that you observed during your inspection of Platform Henry on 8/20/2019, please see below for DCOR's response:

Area of Concern:

Rust and Corrosion throughout the facility:

DCOR's Response: To mitigate this problem , DCOR follows the following API-recommended standards:

- API 510, 570 and 653 for inspections of vessels, process piping and tanks
- API RP 2 SIM for structural inspections
- NACE SP 169/176 for Cathodic protection
- While descaling/cleaning the structure , vessels, tanks or piping by needle gun, grit blasting or by other means, DCOR's policy is to collect all the generated debris on a tarp or a similar material so that no debris goes into the ocean.

If you have any question or need anything further, please let me know.

Regards

Sincerely,

Jay Rao
Environmental Engineer
DCOR, LLC

From: WEISS, MICHAEL <weiss.michael@epa.gov>
Sent: Friday, October 25, 2019 3:56 PM
To: Jay Rao <JRao@dcorllc.com>
Cc: james.salmons@bsee.gov; Kevin Bramley <kbramley@dcorllc.com>
Subject: Platform Henry Inspection Report

Jay,

Please find attached EPA's inspection report for our August 2019 Clean Water Act compliance inspections of Platform Henry. Feel free to contact me with any question.

Best Regards,
Mike

Michael Weiss
Wastewater Section (ENF-3-1)
Enforcement Division
U.S. EPA Region 9
75 Hawthorne Street
San Francisco, CA 94105
415.947.4570

-- IMPORTANT INFORMATION: This e-mail, including all attachments, constitutes an electronic communication within the meaning of the "Electronic Communications Privacy Act, 18 USC 2510" and may not be shown, printed or read by anyone other than the intended recipient(s). This message is confidential and may be legally privileged. If you are not an intended recipient or if you have received this message in error, you are hereby notified that any dissemination, distribution or reproduction of this e-mail is strictly prohibited. If you have received this e-mail in error, please immediately notify us by reply e-mail or telephone at 805-535-2000, then promptly and permanently delete this message. --